

Dematic Support


 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00188659**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00188659

Previous Case ID  11097313Case Owner  Robert RidderingAccount Name Certo Brothers - West Seneca, NYContact Name  Bill MillerStatus  ClosedCategory  ElectricalPriority  3Priority Description  System Operational**Information**

Subject Rapid Route isn't communicating with the PLC. The product stops at 600600.

Description Rapid Route isn't communicating with the PLC. The product stops at 600600.

Resolution  Reterminate 600600 PPI wiring**System Information**

Date/Time Opened 11/30/2009 8:18 PM

Date/Time Closed 12/14/2009 4:08 AM

Created By Robert Riddering, 11/30/2009 8:18 PMLast Modified By Derek Camp, 1/22/2015 8:45 AM**Comments**

Comments

Public Comment	Name	Date Time
<p>While I was getting a ticket going, Bill said the 600600 line just started and the comms is back between the PLC and Rapid Route. He said he would call back if it starts messing up again.</p> <p>2:00am- Bill called back and said 600600 isn't releasing product again. I connected to the PLC and started looking through the code. The only reason I can see why this isn't releasing is because it thinks 600700 isn't empty. Bill said that 600700 is empty though. From looking at the code, the PPI count isn't getting out of the negative numbers, so it thinks it isn't empty. Bill said they made a change to the layers for this product on there end and that matbe we need to make a change on our end. I told him I would need to get a hold of the controls engineer to see if that can be done through the PLC or maybe this would be done through the RapidRoute. I called Tony D. back and he did see that it shows in RapidRoute that there is suppose to be 12 layers, but Bill said it was changed to 11 layers.</p> <p>Bill said they will work through this tonight and have the people during the day call back to figure this out.</p>	Robert Riddering	9/22/2014 9:38 AM
<p>Received a call from Bill Miller, he wants a status on what's going on with this issue. Assigned call Mike Raymond.</p>	Silvestre Luevano	9/22/2014 9:38 AM
<p>I reviewed the call per Sly's request: I found it to be the same as 11095598.</p> <p>I called Bill and discussed the details and directed him to CC6 and the 600600 PPI / power supply and wiring back to the PLC. I directed him to I:002/3 with the direction of card slot 2 terminal 3 and directed him to monitor the input when all of the lines are running the 4 PPI inputs should flash at the same fast blink probably almost solid.</p> <p>In the last call replacing the PPI did not correct the issue and actualy made it worse.</p> <p>They are going to locate the input wiring and reterminate to determine if the issue is resolved.</p>	Michael Raymond	9/22/2014 9:38 AM
<p>Follow up with John M.</p> <p>Left V-Mail.</p>	Michael Raymond	9/22/2014 9:38 AM

☐ [Back To Top](#)

Always show me ☐ [more](#) records per related list