Dematic Support | Joe Certo

Home Cases Contacts

Case
00057988

Printable View

« Back to List: Cases

Case Detail

Case Number	00057988	Previous Case ID	11082303
Case Owner	Bobbie Wilkerson		
Account Name	Certo Brothers - West Seneca, NY		
Contact Name	Bill Miller		
Status	Closed		
Category	Electrical		
Priority	3		
Priority Description	System Operational		

Information

Subject	Getting a deceleration error on T-Car.
Description	Getting a deceleration error on T-Car.
Resolution	Align TC+4300A East End Of Aisle eye. I:13/8.

System Information

Date/Time Opened	12/16/2008 9:41 PM	Date/Time Closed	12/17/2008 3:15 PM
Created By	Bobbie Wilkerson, 12/16/2008 9:41 PM	Last Modified By	Derek Camp, 1/22/2015 8:39 AM

Comments

Comments

Public Comment	Name	Date Time
Connected to PLC. Saw the decel fault was turning on. There are several thing that latch in the output. Will get with day shift when they arrive.	Bobbie Wilkerson	9/22/2014 10:09 AM
I worked with John to identify the cause of the Decel fault. I found in CC14 ladder 3 rung 196 the TC+A East End Of Aisle photo eye I:13/8 was not aligned correctly, Causing the TC+4300 Decel Fault Latch to be set. We aligned the photo eye and the fault did not reoccure.	Michael Raymond	9/22/2014 10:09 AM

Back To Top

Always show me more records per related list

Copyright © 2000-2015 salesforce.com, inc. All rights reserved. | Privacy Statement | Security Statement | Terms of Use