

Dematic Support

 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00071128**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00071128

Previous Case ID  11105093Case Owner  Bud Van SullichemAccount Name Certo Brothers - West Seneca, NYContact Name  Bill MillerStatus  ClosedCategory  ElectricalPriority  2Priority Description  System partially down**Information**

Subject No buffers will release after a power outage

Description No buffers will release after a power outage

Resolution .**System Information**

Date/Time Opened 6/2/2010 8:46 PM

Date/Time Closed 6/4/2010 3:45 AM

Created By Bud Van Sullichem, 6/2/2010 8:46 PMLast Modified By Derek Camp, 1/22/2015 8:48 AM**Comments**

Comments**Public Comment**

Connected to PLCs in CC-02, CC-03, and CC-06 and toggled the bits shown in the attachments to get the buffers to start releasing again.
All began releasing except West Lower, because product is not there yet.
Waiting for Bill to verify that it is working.
Releasing now.
Bill wants the call left open for a few hours as it is still storming there.

Name

Bud Van
Sullichem

Date Time

9/22/2014
9:49 AM

Bill called back and said the 1-2 merge wouldn't run.
I connected to CC-05 and started looking at the logic.
At that point Bill said they manually actuated the contactors for 702300 and 702301.
Running now.

Bud Van
Sullichem

9/22/2014
9:49 AM

☐ [Back To Top](#)

Always show me ☐ [more](#) records per related list