

Dematic Support

Joe Certo

[Home](#)
[Cases](#)
[Contacts](#)
 Case
00110495
[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00110495

Previous Case ID 11182840Case Owner Bud Van SullichemAccount Name Certo Brothers - West Seneca, NYContact Name John Maddigan (Operations)Status ClosedCategory ElectricalPriority 4Priority Description Intermittent Problems**Information**

Subject Merge releasing randomly

Description Merge releasing randomly

Resolution removed old files from rr .
d: drive had 0 megs**System Information**

Date/Time Opened 7/12/2013 12:16 AM

Date/Time Closed 7/15/2013 6:59 AM

Created By Bud Van Sullichem, 7/12/2013 12:16 AMLast Modified By Derek Camp, 1/22/2015 9:26 AM**Comments**

Comments

Public Comment	Name	Date Time
<p>While connecting to CC-04, which controls the merge, John mentioned that he is getting a large number of errors in the RR scrollinf log. Brought Tom on the call to check out the RR. He tried restarting some processes, but they don't seem to be starting back up. Checked the DB Server, and found it was out of disk space, so he will clear some up. 4:45am - I turned the call over to Tom.</p>	Bud Van Suilichem	9/22/2014 10:06 AM
<p>connected to rr found 0 megs on d: drive cleared 900 megs from last months logs. they are back to work suggested reboot of rr before next shift. called back east buffer not releaseing toggled bits . then releasing two at a time restarted buffers.</p>	Thomas Harris	9/22/2014 10:06 AM

[Back To Top](#)

Always show me [more](#) records per related list