

Dematic Support

Joe Certo

[Home](#)
[Cases](#)
[Contacts](#)
 Case  
**00112307**
[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00112307

Previous Case ID  11186300Case Owner  Steven CarpenterAccount Name Certo Brothers - West Seneca, NYContact Name  Bill MillerStatus  ClosedCategory  ElectricalPriority  3Priority Description  System Operational**Information**

Subject need release bit for buffer lane reset CC3 Lane1

Description need release bit for buffer lane reset  
CC3 Lane1Resolution  LAD 14:37 - Lower Buffer Release Command One Shot. N157:32 is suppose to get set to 2 after the command is moved. N137:32 was set to 2 but the command had not been moved. To restart the release I set it back to 1. I set bit to 1.**System Information**

Date/Time Opened 8/28/2013 9:41 AM

Date/Time Closed 8/30/2013 10:40 AM

Created By Steven Carpenter, 8/28/2013 9:41 AMLast Modified By Derek Camp, 1/22/2015 9:28 AM**Comments**

**Comments**

Public Comment	Name	Date Time
transfer to Dave	Steven Carpenter	9/22/2014 9:12 AM
LAD 14:37 - Lower Buffer Release Command One Shot. N157:32 is suppose to get set to 2 after the command is moved. N137:32 was set to 2 but the command had not been moved. To restart the release I set it back to 1. I set bit to 1.	David Pickel	9/22/2014 9:12 AM

 [Back To Top](#)Always show me  [more](#) records per related list