00116324 ~ Dematic Support Dematic Support			Joe Certo	
	I			
lome <mark>Cases</mark> Col	ntacts			
Case Case			Printable View	
00116324				
« Back to List: Cases				
Case Detail				
Case Number	00116324	Previous Case ID	11193915	
Case Owner	lan Dudek			
Account Name	Certo Brothers - West Seneca, NY			
Contact Name	John Maddigan (Maint)			
Status	Closed			
Category	Electrical			
Priority	3			
Priority Description	System Operational			
Information				
Subject	Alarm on north mole car CC1			
Description	Alarm on north mole car CC1			
Resolution	Site reinstaleld their VFD and was running	ng again. They have the para	ameter to disable the error is needed.	
System Information				
Date/Time Opened	11/27/2013 6:28 AM	Date/Time Closed	12/16/2013 4:32 AM	
Created By	lan Dudek, 11/27/2013 6:28 AM	Last Modified By	<u>Derek Camp</u> , 2/28/2015 1:04 PM	
Comments				

Comments

Public Comment	Name	Date Time
Found the PLC program and I keep losing connecion to the processor. The site was getting decell faults on the Mole car and I was able to have them hit a EStop and once they cleared the EStop it would run and then reach top speed and then fault out again. I suggested that they repalce the Powerflex 700 and after that it was working in Manual mode they are testing it out and will call back,	Jamie Chrisman	9/22/2014 10:07 AM
John called back saying they replaced the PowerFlex 700 and the car will move manually but will not move when in automatic mode. Please call John back at 716 609 2261	Wade Shindorf	9/22/2014 10:07 AM
I contacted the site again and we are having communication problems between the powerflex and the micro logix PLC. The site is connecting heir laptop up to the PLC since we can not go online with it. 3:45 - I had the site default the VFD and go through their site setting again. The site reinstalled the old VFD and the Mole car started working again and they received the Decel fault but they cleared it and were running again. The VFD that they installed was used and has a problem with it.		9/22/2014 10:07 AM
Parameter 238 bit 6 will disable the Decel Inhibit - Disable the error.		

8/14/15

Back To Top

Always show me more records per related list

Copyright © 2000-2015 salesforce.com, inc. All rights reserved. | Privacy Statement | Security Statement | Terms of Use