


Dematic Support

 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00180215**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00180215

Previous Case ID  11054468Case Owner  Robert RidderingAccount Name Certo Brothers - West Seneca, NYContact Name  Bob hammerStatus  ClosedCategory  SoftwarePriority  3Priority Description  System Operational**Information****Subject** East upper dynamic lane is not replenishing.**Description** East upper dynamic lane is not replenishing.**Resolution**  Lane is designed not to replen because too few item are required. Items should be coming from static lane 11 but the "InLine" count shows zero on lane 11. The fix is for the operator to reset the lane and provide a count of how many cases are contained.**System Information****Date/Time Opened** 5/16/2007 3:16 AM**Date/Time Closed** 5/17/2007 12:10 PM**Created By** Robert Riddering, 5/16/2007 3:16 AM**Last Modified By** Derek Camp, 1/22/2015 8:28 AM**Comments**

☐ [Back To Top](#)

Always show me ☐ [more](#) records per related list