

Dematic Support


 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00180885**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00180885

Previous Case ID  11059728Case Owner  David AbbeyAccount Name Certo Brothers - West Seneca, NYContact Name  John Maddigan (Maint)Status  ClosedCategory  ElectricalPriority  3Priority Description  System Operational**Information**

Subject PLC: CC6: Super buffer Auto Fill Mode, Lines indicated as full on the panel vi

Description PLC: CC6: Super buffer Auto Fill Mode, Lines indicated as full on the panel view.

Resolution  Toggle 600800 package present photo eye.**System Information**

Date/Time Opened 8/28/2007 5:33 AM

Date/Time Closed 8/29/2007 3:13 AM

Created By David Abbey, 8/28/2007 5:33 AMLast Modified By Derek Camp, 1/22/2015 8:31 AM**Comments**

**Comments**

Public Comment	Name	Date Time
Trying to perform an autifill on the super buffer in CC6. It keeps telling them that the bins are full but they are not physically full and product is not moving.	David Abbey	9/22/2014 10:09 AM
The line stopped and when he restarted he got the error on the PanelView that lane 3 is full. It is not full.		
Pulled Michael Raymond on the line.	David Abbey	9/22/2014 10:09 AM
Certo had a power failure last night. The photo eye and the sorter need to communicate within 3 seconds and if that does not happen the plc registers a lane full. There seems to be an issue with the comms from the PE and the PLC.	David Abbey	9/22/2014 10:09 AM
I discussed the issue with John and found that when he attempts to switch the fill to lane 2 he gets a lane full indication on the panel view.	Michael Raymond	9/22/2014 10:09 AM
I investigated the logic and directed John to the lane and he went and flagged the photo eyes on the lane and found that when he flagged the index photo eye the line started.		
I reviewed the logic and found that he was missing the 600800 last box delay stop bit which is driven by the package present photo eye.		
My conclusion is that in the release there was one box missing in the tracking file and the system was waiting for that carton to release before it indexed the next line.		

[Back To Top](#)Always show me ☐ more records per related list