Case: 00182940 ~ Dematic Support 8/14/15 Joe Certo **Dematic Support** Home Cases Contacts Case Case Printable View 00182940 « Back to List: Cases Case Detail Case Number Previous Case ID 00182940 11072903 Case Owner **Bud Van Suilichem Account Name** Certo Brothers - West Seneca, NY **Contact Name** Bill Miller Status Closed Category Electrical Priority **Priority Description** System partially down Information Subject 5-1 Merge not releasing Description 5-1 Merge not releasing Resolution they released a package from the panel view and the merge started to work **System Information** Date/Time Opened 5/29/2008 5:52 PM Date/Time Closed 6/3/2008 10:47 PM Created By Bud Van Suilichem, 5/29/2008 5:52 PM Last Modified By Derek Camp, 2/28/2015 1:05 PM

Comments

Comments

Public Comment	Name	Date Time
Bill says the 5-1 lanes are not releasing. I connected to the PLC in CC-4, and found that the Host Error light is on, and the lines are not releasing. The release id (N111:[N68:0]) is -1, but needs to be zero or above to release. Got Mike to connect to RR while I looked at CC-4. Bill was able to release it manually using a button placed on the panelview by Mahesh. After that the lines continued to release. Mike said he will need to turn over to Mahesh or other BevPro guys in the morning.	Bud Van Suilichem	9/22/2014 9:28 AM
This happens occasionally, but when it does it happens three to four times in a short period of time.	Michael Axdorff	9/22/2014 9:28 AM
10:28 I restarted the MainMerge process but it didn't change the result.		
10:29 they released on package from the panelview and the main merge started to work again?		

□ Back To Top

Always show me more records per related list

Copyright © 2000-2015 salesforce.com, inc. All rights reserved. | Privacy Statement | Security Statement | Terms of Use