

Case **00195006**

[Printable View](#)

[« Back to List: Cases](#)

Case Detail

Case Number 00195006

Previous Case ID 11126201

Case Owner Jeffrey Peterson

Account Name Certo Brothers - West Seneca, NY

Contact Name Bill Miller

Status Closed

Category Electrical

Priority 3

Priority Description System Operational

Information

Subject Needs the lane 5 release bit reset after they pulled an estop on the superbuffer

Description Needs the lane 5 release bit reset after they pulled an estop on the superbuffer.

Resolution Used the RSlogix 5 Pro program to connect to CC06 (10.254.1.06) and toggled N157:12 from 2 to 1.

System Information

Date/Time Opened 7/19/2011 12:36 AM

Date/Time Closed 7/21/2011 6:28 AM

Created By Jeffrey Peterson, 7/19/2011 12:36 AM

Last Modified By Derek Camp, 1/22/2015 8:56 AM

Comments

Comments

| Public Comment | Name | Date Time |
|--|------------------|-------------------|
| 4:30 AM - Used the RSlogix 5 Pro program to connect to CC06 (10.254.1.06) and toggled N157:12 from 2 to 1. - 5:30 AM | Jeffrey Peterson | 9/22/2014 9:25 AM |

[Back To Top](#)

Always show me [more](#) records per related list