

Dematic Support

 Joe Certo[Home](#) **Cases** [Contacts](#)

Case

Case

00228052

[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00228052

Previous Case ID  11211363Case Owner  Jeffrey PetersonAccount Name Certo Brothers - West Seneca, NYContact Name  Bill MillerStatus  ClosedCategory  ElectricalPriority  2Priority Description  System partially down**Information**

Subject Needs the East Lower buffer release bit CC02 toggled.

Description Needs the East Lower buffer release bit CC02 toggled.

Resolution  Toggled N157:32**System Information**

Date/Time Opened 7/29/2014 4:41 PM

Date/Time Closed 7/30/2014 9:45 AM

Created By Jeffrey Peterson, 7/29/2014 4:41 PMLast Modified By Derek Camp, 1/22/2015 9:41 AM**Comments**

Comments**Public Comment****Name****Date Time**

8:40 PM EDT - LAD 14:37 - Lower Buffer Release Command One Shot. N157:32 is suppose to get set to 2 after the command is moved. N157:32 was set to 2 but the command had not been moved. To restart the release I set it back to 1. This didn't work right away. I did it a couple more times. It began working. - 9:00 PM EDT

Jeffrey Peterson 9/22/2014 9:54 AM

Documentation

☐ [Back To Top](#)

Always show me ☐ [more](#) records per related list