

Case **00041522**

[Printable View](#)

[« Back to List: Cases](#)

### Case Detail

Case Number 00041522

Previous Case ID 11055306

Case Owner Bobbie Wilkerson

Account Name Certo Brothers - West Seneca, NY

Contact Name Bill Miller

Status Closed

Category Electrical

Priority 2

Priority Description System partially down

### Information

Subject Lanes not diverting.

Description Lanes not diverting.

Resolution Blown fuse.

### System Information

Date/Time Opened 6/4/2007 5:32 PM

Date/Time Closed 6/4/2007 7:04 PM

Created By Bobbie Wilkerson, 6/4/2007 5:32 PM

Last Modified By Derek Camp, 1/22/2015 8:28 AM

### Comments

**Comments**

Public Comment	Name	Date Time
Lanes not diverting. Connected to the RSC. Fired the divert (#17) manually. The site says the opto did light up, but they are not getting the divert firing. The site is going to further look at the wiring.	Bobbie Wilkerson	9/22/2014 10:01 AM
Site called back and said they found a bad fuse. They replaced, and all is fine.	Bobbie Wilkerson	9/22/2014 10:01 AM

[Back To Top](#)Always show me  more records per related list