

Case  Case **00051879**

[Printable View](#)

[« Back to List: Cases](#)

### Case Detail

Case Number  00051879

Previous Case ID  11071716

Case Owner  Bud Van Sullichem

Account Name  Certo Brothers - West Seneca, NY

Contact Name  Bill Miller

Status  Closed

Category  Electrical

Priority  2

Priority Description  System partially down

### Information

Subject  Lane 4 in Superbuffer not releasing after a motor fault

Description  Lane 4 in Superbuffer not releasing after a motor fault

Resolution  Toggled value in N157:12 from 2 to 1.

### System Information

Date/Time Opened  5/4/2008 6:48 PM

Date/Time Closed  5/5/2008 1:54 AM

Created By  Bud Van Sullichem, 5/4/2008 6:48 PM

Last Modified By  Derek Camp, 1/22/2015 8:35 AM

### Comments

### Comments

Public Comment	Name	Date Time
Bill says they had a motor fault on BT 604100 earlier, and after clearing the fault, lane 4 won't release. Toggled value in N157:12 from 2 to 1. Everything is releasing now.	Bud Van Suilichem	9/22/2014 10:09 AM

[Back To Top](#)

Always show me  [more](#) records per related list