Dematic Support			Joe Certo
lome Cases Cor	ntacts		
Case 00079455			Printable Vie
« Back to List: Cases			
Case Detail			
Case Number	00079455	Previous Case ID	11119664
Case Owner	Bud Van Suilichem		
Account Name	Certo Brothers - West Seneca, NY		
Contact Name	Bill Miller		
Status	Closed		
Category	Electrical		
Priority	2		
Priority Description	System partially down		
Information			
Subject	5:1 Merge not releasing		
Description	5:1 Merge not releasing		
Resolution	I filtered the labels in the database for 117 RETSEQ values that are not NULL. I clear the PLC. They tested the system and after	ed these status's and the o	controls engineer cleared some things on
System Information			
Date/Time Opened	4/4/2011 7:16 PM	Date/Time Closed	4/14/2011 11:47 AM
Created By	Bud Van Suilichem, 4/4/2011 7:16 PM	Last Modified By	Derek Camp, 2/28/2015 1:05 PM
Comments			

Comments

Public Comment	Name	Date Tim
Connected to CC-04. Looked at logic, but don't see why not releasing. Can release one at a time only. Brought Tom on the call to look at RR. Found an anomaly label. Tom changed the CR to RL, but no help. Looked at a previous call, and saw that Jeff had deleted a duplicate label previously, to reset. 12:30am - Tom deleted it, but still not releasing. 11:10am - Tom conferenced Jerry Grunder on. They decided to bring Mahes on. Icalled and left VM. Jerry will try also. 1:45am - Bill asked me to bring Sylvestre on the call, so I did. Conferenced Mike Axdorf, Paul Berna, and Brad Warmuskerken, at Jerry's requests. 3:00am - Tony found some cases assigned to a pallet that didn't exist any more. He deleted or changed them, and the lines started releasing. Bill said they were releasing very slowly, and no releases from line 2. 3:30am - Had Bill release one from line 2 manually, but all other lines stopped releasing. I changed the value of N68:10 from 5 to 0. At that point the merge started releasing again at normal rate. 4:00am - Monitored for awhile, and it seems to be running normally.	Bud Van Suilichem	9/22/2014 10:04 AM
connected to rr checked for issues using notes cleared label error. still did not clear called tony for help. droped to take other call.	Thomas Harris	9/22/2014 10:04 AM
per Jerry customer up and running at 0400 Tuesday / had combination of mechanical and softwar issues	Steven Carpenter	9/22/2014 10:04 AM
2330 - I connected to the system and looked at the issue. We followed the instruction to remove a anyomolly label from the system.	Tony Dunckel	9/22/2014 10:04 AM
0000 - We continued to have issues. I have looked through all of the logs and notes on the system and there is no definition of what is causing the system to not run.		
0100 - We escalated to Management and attempted to get Engineering on the phone.		
0200 - Be brought on more help attempting to find someone who knows the custome merge logic.		
0300 - We discussed having the customer work the rest of the run manaully. They have almost 10000 cartons left so they do not want to do that.		
0330 - I found a message in the log stating that the label was attempting to induct for pallet 117 however the current pallet was 118. I filtered the labels in the database for 117 and found a couple labels that have a status of U or C that still have RETSEQ values that are not NULL. I cleared these status's and the controls engineer cleared some things on the PLC. They tested the system and after some tweeking they were able to get the system operational.		
0400 - I cleared up the database windows. I removed the log copies and CB file copies I had created. I activated user hide and then backed out of the system.		

Back To Top

Always show me more records per related list

Copyright © 2000-2015 salesforce.com, inc. All rights reserved. | Privacy Statement | Security Statement | Terms of Use