

Dematic Support

 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00082569**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00082569

Previous Case ID  11125487Case Owner  David AbbeyAccount Name Certo Brothers - West Seneca, NYContact Name  John Maddigan (Maint)Status  ClosedCategory  ElectricalPriority  3Priority Description  System Operational**Information**

Subject West Upper Buffer not releasing

Description West Upper Buffer not releasing

Resolution  poked n157:12 to 1.
Now it is releasing.
Monitored operation.**System Information**

Date/Time Opened 7/7/2011 10:27 AM

Date/Time Closed 7/20/2011 11:37 AM

Created By David Abbey, 7/7/2011 10:27 AMLast Modified By Derek Camp, 1/22/2015 8:56 AM**Comments**

☐ [Back To Top](#)

Always show me ☐ [more](#) records per related list

Copyright © 2000-2015 salesforce.com, inc. All rights reserved. | [Privacy Statement](#) | [Security Statement](#) | [Terms of Use](#)