

Dematic Support

 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00178526**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00178526

Previous Case ID  11039905Case Owner  Bud Van SullichemAccount Name Certo Brothers - West Seneca, NYContact Name  Ken CertoStatus  ClosedCategory  MechanicalPriority  3Priority Description  System Operational**Information**

Subject Axle nuts won't stay tight on any of the conveyor in their 4 banks of buffer zon

Description Axle nuts won't stay tight on any of the conveyor in their 4 banks of buffer zones.

Resolution  Escalated to project manager**System Information**

Date/Time Opened 7/22/2006 3:39 AM

Date/Time Closed 7/24/2006 3:41 AM

Created By Bud Van Sullichem, 7/22/2006 3:39 AMLast Modified By Derek Camp, 1/22/2015 8:21 AM**Comments**

Comments

Public Comment	Name	Date Time
Axle nuts won't stay tight on any of the conveyor in their 4 banks of buffer zones. He says he thinks they are installed wrong. (RH/LH). They just noticed the issue on July 19th. Told him we would contact the PM on Monday. PM is Larry Aldrink. Sent him an email.	Bud Van Sullichem	9/22/2014 9:26 AM
Called the PM, Larry Aldrink. He is aware of the problem and is working on it.	Bud Van Sullichem	9/22/2014 9:26 AM

[Back To Top](#)Always show me ☐ more records per related list