Case: 00180270 ~ Dematic Support 8/14/15 Joe Certo **Dematic Support** Home Cases Contacts Case Case Printable View 00180270 « Back to List: Cases Case Detail Case Number Previous Case ID 00180270 11054877 Case Owner Tompkins Conrad **Account Name** Certo Brothers - West Seneca, NY **Contact Name** Bill Miller Status Closed Category Software Priority **Priority Description** System partially down Information Subject rapid route locked up Description rapid route locked up Resolution mahes manually fixed the nocode situation in the DB. The Anomaly was actually on the superput buffer lane. **System Information** Date/Time Opened 5/25/2007 1:04 AM Date/Time Closed 5/25/2007 7:22 AM Created By Gears CRM, 5/25/2007 1:04 AM Last Modified By Derek Camp, 1/22/2015 8:28 AM

Comments

Comments

Public Comment	Name	Date Time
release ID says 1915 and should be minus1	GearsCRM	9/22/2014 9:00 AM
FOLLOWING IS THE WORK BY MAHES RAMADOS: Nick,	Nickolas Pavkov	9/22/2014 9:00 AM
I have just noticed that the Visual Basic installed in the server is either corrupt or attacked by a virus. It is not allowing me to open any projects. This is a serious condition that we need to inform Certo. I have also noticed that the some of the existing exe's are not behaving properly including the display process.		
Mahes		
From: Ramados, Maheswaran Sent: Friday, May 25, 2007 8:42 AM To: Pavkov, Nickolas P Cc: Batts, Anthony Subject: Certo support this morning		
Nick, I have worked on the case further this morning. What I have found is that the case 915259 had some kind of anamoly at the Scanner/PLC . First we got a NO-CODE for that case and then we got the actual barcode. Both the times we responded with a valid release sequence number but we got only one confirmation so the merge is stopped. To resolve this I just reset the duplicate case in the DB and the merge took off. We can make a code change to reset the anomaly cases at the merge. Possibly a button for the operator to reset the anamoly cases.		
04:38:25 16-RRSCN1/Super Sys_Info_005 DB MESSAGE:[SQL Server]Label 915259 got assigned Release Sequence Number 1914 Route: 5420 Stop: 885062 Batch: 0 Pick Wave: 0 Pallet ID:0177 04:38:25 16-RRSCN1/Super App_Info_023 SCANNED NO-CODE at scanner: 1 and assigned Release Sequence: 1914. (SUPER)Assumed label:915259 (Seq. # 7) 04:38:25 27-PLCUnsoIDispo App_Info_020 Confirmed label: 915259 at scanner: 1, dvt: 1914. (Seq. # 7) status: SUCCESS(8193)		
04:38:26 16-RRSCN1/Super Sys_Info_005 DB MESSAGE:[SQL Server]GetReleaseSeqNumber: Label 915259 already got assigned release sequence number,this is duplicate label 04:38:26 16-RRSCN1/Super Sys_Info_005 DB MESSAGE:[SQL Server]Label 915259 got assigned Release Sequence Number 1914 Route: Stop: Batch: 0 Pick Wave: 0 Pallet ID: 04:38:26 16-RRSCN1/Super App_Info_023 SCANNED Label: 915259 at scanner: 1 and assigned Release Sequence: 1914. (SUPER) (Seq. # 8)		
Mahes		
customer says the merge will not release. I dialed in and looked around. After some time, I tried to call and page Mahes. Got VM, left message. I continued to research. We tried to reset the merge on the merge status screen a few times, this did not help. Also attempted to have customer force a few boxes thru the lanes, status changed on status screen but it would not take off. Mahes called me back and he dialed in and found a nocode with no response from the PLC was causing the issue.	Nickolas Pavkov	9/22/2014 9:00 AM

□ Back To Top

Always show me more records per related list

 $Copyright @\ 2000-2015\ sales force.com, inc.\ All\ rights\ reserved.\ |\ \underline{Privacy\ Statement}\ |\ \underline{Security\ Statement}\ |\ \underline{Terms\ of\ Use}$