

Dematic Support

 Joe Certo[Home](#) **Cases** [Contacts](#)Case **00201213**[Printable View](#)[« Back to List: Cases](#)**Case Detail**

Case Number 00201213

Previous Case ID  11146985Case Owner  Jeffrey PetersonAccount Name Certo Brothers - West Seneca, NYContact Name  John Maddigan (Operations)Status  ClosedCategory  MechanicalPriority  1Priority Description  System Down**Information**

Subject CC4 Merge 5 to 1 merge having a problem. Encoder fault

Description CC4 Merge 5 to 1 merge having a problem. Encoder fault

Resolution  Loose Lovejoy coupler**System Information**

Date/Time Opened 4/1/2012 10:21 PM

Date/Time Closed 4/2/2012 9:08 AM

Created By Jeffrey Peterson, 4/1/2012 10:21 PMLast Modified By Derek Camp, 2/28/2015 1:03 PM**Comments**

Comments

Public Comment	Name	Date Time
Getting encoder fault on unit #1050. Having them check the PPI for that line.	Bobbie Wilkerson	9/22/2014 9:38 AM
coupler had backed out. Belt not turning.	Bobbie Wilkerson	9/22/2014 9:38 AM

[Back To Top](#)Always show me ☐ [more](#) records per related list